



## **Table of contents**

	Page
Overview	2
Specification/ application	3
NB 4000	4
Options/ Accessories	6
Dimensions/ materials	7
Spare parts	9
Electrical installation	 11

Subject to change.

All dimensions in mm (inches).

All prices in Euro ( $\in$ ) or USD (\$), excluding VAT.

All EURO prices are EXW Betzigau, all USD prices are EXW Memphis, excluding packaging costs.

Valid: From 01.04.2019 until 31.03.2020, unless otherwise agreed.

By publishing this selection list all other lists become invalid.

We assume no liability for typing errors.

Different variations to those specified are possible. Please contact our technical consultants.







#### **Overview**

#### **Features**

Continuous level measurement of solids applications

#### Process

- Independent of bulk material properties
- Accurate measurement

#### Service

- Simple installation and commissioning
- Rope and tape version with long service life
- Low maintenance

#### **Approvals**

- Approval for use in Hazardous Areas
- 2011/65/EU RoHS conform

#### Mechanics

- Measurement range up to 30 m (100 ft)
- 11/2" process connection possible
- Aiming flange to be mounted directly on a flat silo roof
- Internal tape cleaner for difficult materials

#### **Electronics**

- Micro processor controlled measurement
- Diagnostic possibilities
- Output 4-20 mA/ Modbus
- Two programmable Relay (can be used as Counting/ reset pulse output or as Failure/ Upper stop position)



NB 4100 Rope version Fig. with flange DN100 and PVC sensor weight



NB 4200
Tape version
Fig. with thread connection
and stainless steel sensor
weight



NB 4100 Rope version Fig. with aiming flange and stainless steel sensor weight with pin






## Specification / application


## Specification


Process	Measurement range	15 m (50 ft) or 30 m (100 ft)	
	Process temperature	80°C (176°F)	
	Process overpressure	-0.2 +0.2 bar (-3.0 + 3.0 psi)	
	Min. powder density	>300 g/l (18 lb/ft³)	
Electronics	Power supply	AC version 115 V or 230 V 50 - 60 Hz DC version 20 28 V	
	Output	4-20 mA	
		2 relais (optional)	
		Modbus RTU	
Approvals Dust Ex		ATEX 1/2D	
		FM Cl. II, III Div. 1, TR-CU	
	Ordinary Location	CE, FM, TR-CU	

## Application

#### Solids measurement







For measurements through a long pipe in a double chamber silo we recommend the use of NB 4200 (tape version).



## **NB 4000**

#### **NB 4100**

Rope version (fig. with flange DN100 and PVC sensor weight)



#### NB 4200

Tape version (fig. with thread connection and stainless steel sensor weight)



#### Cable entries (by default)

Depending on selected version (options see pos.26):

CE, ATEX, Screwed cable gland: 1x M25 x 1.5 and 1x M20 x 1.5 TR-CU 1x M25 x 1.5 and 1x M20 x 1.5

Open conduit ANSI B1.20.1: 1x NPT %" and 1x NPT %" Blindplug: 1x NPT %" and 1x NPT %" and 1x NPT %" FM

Blindplug:

**Dimensions** see page 7





## **NB 4000**

pos.1	Basic type
	C NB 4100 Rope version
	D NB 4200 Tape version
pos.2	Certificate
	0 CE (1)
	W ATEX II 1/2 D
	M FM general purpose
	N FM Class II, III Div.1 Group E-G E TR-CU Ex ta/tb IIIC T! Da/Db X
pos.3	Measurement range
	1 15 m (50 ft)
	2 30 m (100 ft)
pos.4	Power supply/ Signal output
	1 230 V 50 - 60Hz 4-20 mA
	4 230 V 50 - 60Hz Modbus •
	2 115 V 50 - 60Hz 4-20 mA
	5 115 V 50 - 60Hz Modbus 3 20 28 V DC 4-20 mA
	3 20 28 V DC 4-20 mA
pos.5	Process connection
	A Thread R 1½" tapered EN 10226-1
	B Thread NPT 1½" tapered ANSI B1.20.1
	X Flange DN100 PN16 (EN 1092-1) and flange 4" 150lbs ANSI B16.5 (unit is fitting to this flange)
	Y Flange 2" and flange 3" 150lbs ANSI B16.5 (unit is fitting to this flange)  W Aiming flange (to be mounted directly to the silo roof) (5)
pos.6	Sensor weight (2)
	Y without <sup>®</sup>
	A PVC (4)
	C Stainless steel
	E Folding cover
Basic type	
NB 400	<b>←</b> Order code

All positions are available in special design (use code "Z").

<sup>&</sup>lt;sup>(1)</sup> TR-CU (Ordinary Locations) included

<sup>(2)</sup> For use in Hazardous Locations (Dust Ex): It must be ensured, that no static discharge from the material surface can occur. Sensor weights, which can be used in case of possible static discharge, on request.

<sup>(3)</sup> Only for tape version. Including mounting set for sensor weight (see page 9: Sensor weights).

 $<sup>^{(4)}</sup>$  Does not fit through a 1½" nozzle, must be mounted after fixing the unit to the silo.


<sup>(5)</sup> Mounting without a socket. Including fixing material (screws, sealing etc.).





## **Options / Accessories**

### **Options**



#### **Accessories**

Minimum order value for spare parts or accessories is 75 €.

### Fixing material for mounting the unit on a flange

zu107000 4 bolts M16 x 60, 8 washers, 4 nuts. Stainless steel.

### Sealings for mounting the unit on a flange

di300125Flange sealing for DN100 PN16/ 4" (neoprene)di300127Flange sealing for 2"/ 3" 150lbs (neoprene)


#### Adapter NPT 11/2" to NPT 3"

zu103100 Thread tapered ANSI B1.20.1, aluminium ......


#### Cable gland

 em400589
 Cable gland with 2 inputs. M25 x 1.5, clamping range 2x ø4.5-7 mm, -20 ... +70°C
 6

 em400573
 Cable gland, M20 x 1.5, clamping range ø6-12 mm, -40 ... +70°C
 6



Weather protection cover



Pin for sensor weight POM or 1.4305 (303)



Adapter NPT 11/2" to NPT 3"







Cable gland with 2 inputs




## **Dimensions and materials**


## **Basic unit**








#### Process connection: Flange



Process connection: Aiming flange

To be screwed directly to the silo roof 0° - 50° adjustable Including screws, nuts and sealing



Flange plate outside dimensions: Width x Heigth: 120 mm x 180 mm (4.7" x 7.1")

#### Dimensions

X = Length to bottom of sensor weight (in upper stop position, see next page)		
<b>A</b> = Length of socket pipe 100 mm (3.9") Optional 200 mm (7.9")/ 500 mm (19.7")/ 1,000 mm (39.4")		
Flanges		
fitting to: DN100 PN16/ 4" 150lbs	Lk = Ø180 - 190.5 mm (Ø7.1 - 7.5") slot d2 = Ø19 mm (Ø0.75")	
fitting to: Lk = Ø120.7 - 152.4 mm (Ø4.75 - 6.0") slot d2 = Ø19 mm (Ø0.75")		
Rope	ø1.0 mm (ø0.04")	
Таре	12 x 0.2 mm (0.47 x 0.008")	

#### Materials


Housing outside	Aluminium, powder coated		
Housing inside	Aluminium		
Thread/ flange	Aluminium		
Aiming flange	Aluminium/ 1.4301 (301)		
Rope	1.4401 (316)		
Таре	1.4310 (301)		



## **Dimensions and materials**

### Sensor weights

#### Rope version



1.4305 (303)

1.4310 (301)

PA Canvas

380 x 380 mm (15 x 15")

Material: 1.4310 (301)/ 1.4305(303)/ PA canvas


For material densitiy >20 g/l (1.2 lb/ft³)

Fits through 1½" mounting hole

Folding cover

All sensor weights: 1,6 kg (3.5 lbs)

#### Tape version



Fixing elements between tape and sensor weight: aluminium/ 1.4305 (303)

All sensor weights: 1.6 kg (3.5 lbs)  $380 \times 380 \text{ mm (15} \times 15")$  Material: 1.4310 (301)/ 1.4305(303)/ PA canvas For material densitiy  $\,>\!20$  g/l (1.2 lb/ft³) Fits through 1½" mounting hole





## **Spare parts**

Minimum order valu	ue for spare part	s or access	sories is 75 €.	
Roller				
sl103239	Rope roller with 1	5 m rope		•
sl103240	Rope roller with 3			•
sb103239	Tape roller with 15			•
sb103240	Tape roller with 30	•		•
Sensor weights				
_	delivered incl. moun	ting parts for	proper fixing to the rope/ tape and excl. rope/ tape	
For rope ve	rsion:			
sl103231				•
sl103232	·			•
sl103233	Stainless steel wi	thout pin		•
sl103234	Stainless steel wi	th pin		•
sl103235	Folding cover			•
For tape ve	rsion:			
sb103231				•
sb103232				•
sb103233	•			•
sb103234	Stainless steel wi	th pin		•
sb103235	Folding cover			•
•	t without sensor	weight		
sl100280	For rope version			•
zu108030	For tape version			•
Motor				
gm103202	Motor			•
Electronics				
pl103690	230 V 50 - 60 Hz	4-20 mA	without 2 Relais (1)	•
pl103691	230 V 50 - 60 Hz	4-20 mA	with 2 Relais (1)	•
pl103696	230 V 50 - 60 Hz	Modbus	without 2 Relais (1)	•
pl103692	115 V 50 - 60 Hz	4-20 mA	without 2 Relais (1)	•
pl103693	115 V 50 - 60 Hz	4-20 mA	with 2 Relais (1)	•
pl103697	115 V 50 - 60 Hz	Modbus	without 2 Relais (1)	•
pl103694	20 28 V DC	4-20 mA	without 2 Relais (1)	•
pl103695	20 28 V DC	4-20 mA	with 2 Relais (1)	•
Required info	ormation: Rope or T	ape version; n	measuring range 15 m or 30 m; evt. further menue presettings.	
Internal Heater (2)				
		_		
em100373	680 Ohms		supply 230 V 50 - 60 Hz	•
em100374	220 Ohms	'	supply 115 V 50 - 60 Hz	•
em100375	8.2 Ohms	For power s	supply 20 28 V DC	•

<sup>(2)</sup> Used for replacement for already mounted heater.
In case of re-fitting the Internal Heater, the electronics must include components for the Internal Heater Control (please contact factory).



Weather protection cover zu400217

<sup>(1)</sup> Implements the electronic components needed to control the Internal Heater (needed for option pos.22)




## **Spare parts**


## Sensor weights/ Mounting set

All sensor weights are delivered including stated parts for proper fixing to the rope/ tape


#### Rope version




#### Tape version



### **Electronics**




**Motor** 



Internal heater



## Weather protection cover








## **Electrical installation**

### Version 4-20 mA

#### **Terminal location**



Internal terminals for motor and heater

#### Terminals for:

- Power supply
- Signal input:
   Start of measurement
   Measurement interruption
- Signal output: 4-20 mA Relais

Note: Terminal 30 and 31 not used

1.5 .. 2.5 mm<sup>2</sup>

(AWG 15 .. 13)

0.14 .. 2.5 mm<sup>2</sup>

(AWG 26 .. 14)

#### Power supply

# 


**AC** version

0.75 .. 2.5 mm<sup>2</sup> (AWG 18 .. 13)

AC or DC supply depending on ordered version

230 V or 115 V 50 - 60 Hz

### DC version





20 .. 28 V DC

## Signal input:

#### Start of measurement

Measurement interruption





Measurement interruption in case of filling. If used, remove factory provided connection.








## **Electrical installation**

Signal output: 4-20 mA




\* CAUTION:

If connecting to a PLC with isolated (floating)

4-20 mA input, the "-" line must be connected to
ground of the PLC. See user manual of the PLC.


Signal output: Relais (optional)



max. 250 V AC, 2 A, 500 VA, non inductive

## **Version Modbus**

#### **Terminal location**



Internal terminals for motor and heater

Terminals for:

- Power supply
- Signal input: Measurement interruption
- Signal output:
   Modbus




Continuous level measuring system **NB 4000** 

Selection list



### **Electrical installation**

#### Power supply



0.75 .. 2.5 mm<sup>2</sup> (AWG 18 .. 13)

230 V or 115 V 50 - 60 Hz


Signal input: Measurement interruption



0.14 .. 2.5 mm<sup>2</sup> (AWG 26 .. 14)


Measurement interruption in case of filling. If used, remove factory provided connection.

## Signal input: Full detector




0.14 .. 2.5 mm<sup>2</sup> (AWG 26 .. 14)

#### Modbus network



Wiring according to Modbus standards



#### Setting Biasing and Termination Resistor

For use of NB 4000 units in a external Modbus network, it is possible to set Biasing and Termination Resistor on each unit as required.

Biasing	OFF*	OFF	ON	ON
Termination Resistor	OFF*	ON	OFF	ON









\*factory provided

DIP Switch position:





Side view

